## **Test Reports by SABS on Klingshield Window Films for Distortion, Impact** and Scratch Resistance

Dr Lategan Road Groenkloof Private Bag X191 Pretoria 0001 Republic of South Africa Telegrams Comparator Telex 3626 SA Telephone 44-1121

Your reference Our reference Enquiries Extension

17/10/51 D A van As

Date



SABS South African Bureau of Standards

Klingshield SA (Pty) Ltd P 0 Box 64095 HIGHLANDS NORTH 2037


MPACT TEST

0611/8684/78 on SAFETY GLAZING MATERIAL

REMARKS

After fracture of the treated panes the glass fragments remained attached to the plastics film in all cases. In the number of cases where impact testing was continued after initial fracture of the glass the pane eventually started pulling out of the frame and the testing had to be discontinued, but apart from a few small splinters of glass no large fragments became dislodged from the film and the film itself remained intact.

One photograph each of the untreated and treated panes after impact are included to illustrate the typical pattern of fracture.



On left abrasion test with
Klingshield film only showing
scratches after 100 cycles to be 2.79%
On right ordinary film after 100 cycles
showing 90% scratching



Klingshield personel in discussion with SABS member



Report no. 0611/8684/78 Treated glass pane after impact glass fragments adhere to the plastic film holding the glass in place

## Test Reports by SABS on Klingshield Window Films for Distortion, Impact and Scratch Resistance

